

# Reclamation Inspection

02/13/2017

Operator: Ward & Son\* Alfred #94300

Location ID: 400509

Inspection Doc. Number: 682501665

Washington County, CO

NESW Section 19 T2S R49W

Aaron Trujillo  
Reclamation Specialist  
COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: Ward & Son\* Alfred #94300  
Location ID: 400509



**Photo 1:** Photo of GPS verifying location.

Inspection Photos  
Operator: Ward & Son\* Alfred #94300  
Location ID: 400509



**Photo 2:** Photo taken from the west end of the location, facing northeast. Photo shows vegetation over the reclamation area.



**Photo 3:** Photo taken from the west end of the location, facing southeast. Photo shows vegetation over the reclamation area