

Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Prior photo for comparison purposes



Photo 1: No contents, capacity on production tank



Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Prior photo for comparison purposes



Photo 2: Stained soil has been remediated



Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Prior photo for comparison purposes



Photo 3: Stained soil at exhaust



Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Prior photo for comparison purposes



Photo 4: Stained soil at engine

Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Photo 5: Sign for prior operator



Photo 6: Decal for prior operator



Inspection Photos
Location Name: Susie 11-9
API: 05-123-10463



Photo 7: Wellhead sign is for prior operator



Photo 8: Stained soil at drain

