

Construction and Stormwater Inspection

February 13, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
#47120

Location ID: 449025

Weld County, CO

NWNW Section 35 T3N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CHICA
Location ID: 449025



Photo 1. Photo taken from the entrance of location, facing North. Vehicle tracking pad installed with cattle guard. BMP appears to be properly functioning.



Photo 2. Photo taken from the northern location, facing South. Topsoil salvaged and stored along the eastern perimeter.

Inspection Photos
Location Name: CHICA
Location ID: 449025



Photo 3. Photo taken from the northeast location, facing South. Ditch and berm BMP installed around perimeter of location.



Photo 4. Photo taken from the southern location, facing West. Ditch and berm BMP installed around perimeter of location.

Inspection Photos
Location Name: CHICA
Location ID: 449025



Photo 5. Photo taken from the southwest location, facing East. Sediment trap is IN-PROCESS of being constructed.



Photo 6. Photo taken from the southwest location, facing South. Ditch and berm BMPs appears to be damaged from equipment traffic. Need to repair BMP per Rule 1002.f.

Inspection Photos
Location Name: CHICA
Location ID: 449025



Photo 7. Photo taken from the southwest location, facing North. Ditch and berm BMP installed along perimeter of location. Ensure all portions of the berm are properly compacted to manage pollutant contributions to stormwater runoff from unconsolidated soil material.



Photo 8. Photo taken from the northwest location, facing East. Ditch and berm BMP installed along perimeter of location.

Inspection Photos
Location Name: CHICA
Location ID: 449025



Photo 9. Photo taken from the northern location, facing West. Sediment trap is IN-PROCESS of being constructed.