

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/17/2017

Submitted Date:

02/17/2017

Document Number:

674004866**FIELD INSPECTION FORM**
 Loc ID 330490 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251393	WELL	PR	07/14/2010	OW	123-19196	HSR-CAMP 15-18	PA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Basic Rig 1652		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 251393 Type: WELL API Number: 123-19196 Status: PR Insp. Status: PA

CementCement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 7000Cement Volume (sx): 40 Sacks

Good Return During Job: _____

Cement Type: GComment:

At time of inspection, crew had completed running scraper to bottom of hole and were waiting on hydro test contractor. Cement scheduled for PM, plans call for cast iron bridge plug at 7,000 feet.

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

Routine PA inspection.
Company representative on location: Edgar.

carlilec

02/17/2017