



photo 1: Facing northeast toward the location.



photo 2: Facing east toward the location.



photo 3: There were areas that appeared to have compacted soils.



photo 4: South side of the location facing north.



photo 5: North side of the location facing south.



photo 6: East side of the location facing west.



photo 7: There is plastic trash debris left at the location.



photo 8: Facing east toward the surrounding undisturbed vegetation.