

Inspection Photos
Location Name: Koshak B-4A
API: 05-067-08736
Inspection Number: 680601296



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass (*Pascopyrum smithii*), James galleta (*Pleuraphis jamesii*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).

Inspection Photos
Location Name: Koshak B-4A
API: 05-067-08736
Inspection Number: 680601296



Photo 3. View of the northern portion of the interim reclamation area from the northeastern corner facing westward.



Photo 4. View of southern portion of the working area from the southeastern corner facing northwestward. Photo shows revegetation progressing on flat areas of working area, largely comprised of dropseed (*Sporobolus* sp.)