

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2017

Submitted Date:

02/17/2017

Document Number:

674703624**FIELD INSPECTION FORM**

Loc ID 334760 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89044	WELL	PR	10/04/1999	GW	045-07372	UNOCAL GM 43-1	PR
274940	WELL	PR	11/04/2004	GW	045-13442	WILLIAMS GM 543-1	PR
274941	WELL	PR	11/04/2004	GW	045-13441	WILLIAMS GM 443-1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		

Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 89044 Type: WELL API Number: 045-07372 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 274940 Type: WELL API Number: 045-13442 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 274941 Type: WELL API Number: 045-13441 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Compaction	Pass			
Seeding	In Process					
		Ditches	Pass			
		Gravel	Pass			
		Check Dams	Pass			
Compaction	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT