

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2017

Submitted Date:

02/14/2017

Document Number:

675203843**FIELD INSPECTION FORM**

Loc ID 334508	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1401 SEVENTEENTH STREET #1400</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: <u>2</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221964	WELL	PR	02/03/2016	GW	077-08566	MCDANIEL 11-10	PR
273822	WELL	PR	12/01/2014	GW	077-08818	MC DANIEL 11-8	PR
273823	WELL	PR	06/01/2011	GW	077-08817	MCDANIEL 11-9	PR
296116	WELL	PR	12/14/2010	GW	077-09652	MCDANIEL 11-16A	PR
296118	WELL	PR	07/01/2011	GW	077-09654	MCDANIEL 11-9C	PR
296119	WELL	PR	07/01/2011	GW	077-09655	MCDANIEL 11-9B	PR
296120	WELL	PR	06/26/2010	GW	077-09650	MCDANIEL 11-10C	PR
296121	WELL	PR	06/18/2010	GW	077-09649	MCDANIEL 11-10A	PR
296124	WELL	PR	12/13/2010	GW	077-09646	MCDANIEL 11-10B	PR
297881	WELL	PR	10/01/2012	GW	077-09709	MCDANIEL 11-9A	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: <u>221964</u>	Type: <u>WELL</u>	API Number: <u>077-08566</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>273822</u>	Type: <u>WELL</u>	API Number: <u>077-08818</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>273823</u>	Type: <u>WELL</u>	API Number: <u>077-08817</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296116</u>	Type: <u>WELL</u>	API Number: <u>077-09652</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296118</u>	Type: <u>WELL</u>	API Number: <u>077-09654</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296119</u>	Type: <u>WELL</u>	API Number: <u>077-09655</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296120</u>	Type: <u>WELL</u>	API Number: <u>077-09650</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296121</u>	Type: <u>WELL</u>	API Number: <u>077-09649</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296124</u>	Type: <u>WELL</u>	API Number: <u>077-09646</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297881</u>	Type: <u>WELL</u>	API Number: <u>077-09709</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Could not do complete stormwater inspection due to snow cover.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401210539	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075616