

Inspection Photos
Location Name: Gunderson 12-10 Pad
Location ID: 334494




Photo 1. Wire fence is damaged. Potential wildlife or livestock hazard. Repair fence by 3/7/17.