



**photo 1:** Facing west toward the location. The vegetation has not adequately established.



**photo 2:** Facing east toward the location. The vegetation has not adequately established.



**photo 3:** There are degraded wattles that remains at the location.



**photo 4:** Facing north toward the location.



**photo 7:** Facing towards the southeast portion of the location. Vegetation has not adequately established.



**photo 8:** Facing north toward the surrounding undisturbed vegetation.