



photo 1: 2015 aerial photo.



photo 2: Facing south along former access road.



photo 3: Facing south toward the location. This area does not have vegetation establishment.



photo 4: South side of the location facing north.



photo 5: Facing west toward the surrounding undisturbed vegetation.