

Inspection Photos
Location Name: Koshak Gas Unit A-
M34N9W8NWSE
API: 05-067-08735
Inspection Number: 680601299



Photo 1. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 2. View of the northwestern portion of the project area from the well pad entrance facing northward. Tracked areas need to be revegetated.

Inspection Photos
Location Name: Koshak Gas Unit A-
M34N9W8NWSE
API: 05-067-08735
Inspection Number: 680601299



Photo 3. View of musk thistles (*Carduus nutans*) in the northern portion of the interim reclamation area.



Photo 4. View of more musk thistles in the eastern portion of the project area.

Inspection Photos
Location Name: Koshak Gas Unit A-
M34N9W8NWSE
API: 05-067-08735
Inspection Number: 680601299



Photo 5. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 6. View of the southern portion of the project area from the southeastern corner facing westward.