

Inspection Photos
Location Name: Gerahart 01-32 1
API: 05-067-06546
Inspection Number: 685302212



Photo 1 Location Sign.



Photo 2 Stained soil on S side of wellhead.

Location Name: Gerahart 01-32 1

API: 05-067-06546

Inspection Number: 685302212



Photo 3 12" X 18" patch of stained soil.



Photo 4 Erosion channel on NW side of location.

Location Name: Gerahart 01-32 1
API: 05-067-06546
Inspection Number: 685302212



Photo 5 Erosion channel on NW side of location.



Photo 6 Erosion channel on NW side of location.

Location Name: Gerahart 01-32 1
API: 05-067-06546
Inspection Number: 685302212



Photo 7 Rilling, erosion channel, and sediment flow on N corner of location.



Photo 8 Sediment flow around Water Can and behind Gas Meter Run along E side of location.

Location Name: Gerahart 01-32 1
API: 05-067-06546
Inspection Number: 685302212



Photo 9 Sediment flow along E side of location.



Photo 10 View along E side of location looking N.