



Photo 1: View of the working area from the southeastern corner facing center.



Photo 2: View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is largely comprised of grasses such as Indian ricegrass (*Achnatherum hymenoides*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3: View of the southwestern portion of the project area from the northwestern edge facing southward.



Photo 4: View of the northwestern portion of the project area from the northwestern edge facing westward.



Photo 5: View of erosion controls in the southwestern corner that need repairs.



Photo 6: View of an erosional channel in the southeastern corner of the project area that needs stabilization measures.



Photo 7: View of an erosional channel approximately 18 inches wide and 12 inches deep that is forming in the northeastern portion of the project area that needs stabilization.