



**photo 1:** Facing north along the former access road. The vegetation is well established along the road.



**photo 2:** Facing north toward the location.



**photo 3:** There is predominately undesirable vegetation at the location.



**photo 4:** Undesirable vegetation growth (Kochia).



**photo 5:** North side of the location facing south.



**photo 6:** Facing south along the east side of the location. Red line indicates the approximate edge of the location and the undisturbed vegetation in the upper left of photo.



**photo 7:** East side of the location facing west.



**photo 8:** Facing east toward the surrounding undisturbed vegetation.