

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/23/2017

Submitted Date:

02/23/2017

Document Number:

674703642**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
416998 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417004	WELL	PR	06/03/2011	GW	045-19433	Puckett GM 444-31	PR
417005	WELL	PR	05/24/2011	GW	045-19434	Puckett GM 44-31	PR
417006	WELL	PR	10/01/2011	GW	045-19435	Puckett GM 344-31	PR
417007	WELL	PR	04/16/2011	GW	045-19436	Puckett GM 14-32	PR
417008	WELL	PR	04/16/2011	GW	045-19437	Puckett GM 514-32	PR
417009	WELL	PR	03/11/2011	GW	045-19438	Puckett GM 43-31	PR
417010	WELL	PR	11/12/2011	GW	045-19439	Puckett GM 334-31	PR
417011	WELL	PR	10/29/2011	GW	045-19440	Puckett GM 434-31	PR
417012	WELL	PR	11/08/2011	GW	045-19441	Puckett GM 333-31	PR
417013	WELL	PR	09/23/2011	GW	045-19442	Puckett GM 433-31	PR
417014	WELL	PR	04/16/2011	GW	045-19443	Puckett GM 414-32	PR
417015	WELL	PR	04/16/2011	GW	045-19444	Puckett GM 443-31	PR
417016	WELL	PR	10/01/2011	GW	045-19445	Puckett GM 34-31	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 15		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		

Comment:	Chemical containers at wells		Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 13			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 9			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	417004	Type:	WELL	API Number:	045-19433	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417005	Type:	WELL	API Number:	045-19434	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417006	Type:	WELL	API Number:	045-19435	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417007	Type:	WELL	API Number:	045-19436	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417008	Type:	WELL	API Number:	045-19437	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417009	Type:	WELL	API Number:	045-19438	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417010	Type:	WELL	API Number:	045-19439	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	417011	Type:	WELL	API Number:	045-19440	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			

Facility ID:	417012	Type:	WELL	API Number:	045-19441	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID:	417013	Type:	WELL	API Number:	045-19442	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID:	417014	Type:	WELL	API Number:	045-19443	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID:	417015	Type:	WELL	API Number:	045-19444	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID:	417016	Type:	WELL	API Number:	045-19445	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Compaction	Pass					
Gravel	Pass					
		Ditches	Pass			
				Material Handling And Spill Prevention	Pass	
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT