

# Reclamation Inspection

02/22/2017

Operator: Vaughey & Vaughey #92950

Location ID: 405138

Inspection Doc. Number: 682501690

Weld County, CO

SENESection 33 T8N R59W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos  
Operator: Vaughey & Vaughey #92950  
Location ID: 405138



**Photo 1:** Photo taken southeast of the well pad. Photo shows pipe sticking out of ground.



**Photo 2:** Photo taken south of the well pad. Photo shows cable debris remaining on location.

Inspection Photos  
Operator: Vaughey & Vaughey #92950  
Location ID: 405138



**Photo 3:** Photo shows concrete pad remaining at well.




**Photo 4:** Photo taken at the well pad. Photo shows what appears to be stained soil found on location.

Inspection Photos  
Operator: Vaughey & Vaughey #92950  
Location ID: 405138



**Photo 5:** Photo taken north of the location. Photo shows concrete pad remaining.

Inspection Photos  
Operator: Vaughey & Vaughey #92950  
Location ID: 405138



**Photo 5:** Aerial image showing approximate locations of the preceding photos found on location.