

Photo#1:

Overview of Location to South from River Bluff Road. Arrow indicates ongoing Pipeline Construction.



February 21, 2017

Photo#2:
BMPs along Access Road scheduled for Repair



Photo#3:



February 21, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: URSA BMC D Pad Loc#446582

Photo#4:

View over Location from SE To NW .



Photo#5:

View over Location East to West



February 21,2017

Photo#6:

Wattles installed at SW Corner of Location



Photo#7:

Dirt work on Ditch and Berm Construction at East Perimeter



February 21,2017

Photo#8:

View to North of Pipeline Construction at West side of Location. Flagged Stake is Limit of Disturbance indicator for O&G Location.



February 21,2017