

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/24/2017

Submitted Date:

02/24/2017

Document Number:

674703662**FIELD INSPECTION FORM**

Loc ID 335398 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-263-2716 | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 269327 | WELL | PR | 12/30/2003 | OW | 045-09350 | GM 334-27 | PR |
| 274269 | WELL | PR | 07/06/2005 | GW | 045-13344 | GM 534-27 | PR |
| 274270 | WELL | PR | 03/30/2005 | GW | 045-13343 | GM 434-27 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|------------------------------------|----------|------|---------|--------|
| | | | | | |
| Comment: | Shared facilities with GM34-27 pad | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 269327 Type: WELL API Number: 045-09350 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID: 274269 Type: WELL API Number: 045-13344 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID: 274270 Type: WELL API Number: 045-13343 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well on plunger lift

Corrective Action:

Date: