

Photo#1:
View over Location to East



February 16, 2017

Photo#2:

Debris remains on Location.



Photo#3:



February 16,2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chesapeak Oldland PA API#103-07411

Photo#4:

Risers / Flowlines remain on Location.



Photo#5:



February 16,2017

Photo#6:

Livestock impact may be preventing establishment of Vegetation and generating conditions favorable to Weed establishment.



February 16,2017