

Construction and Stormwater Inspection

February 22, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
#47120

Location ID: 449025

Weld County, CO

NENW Section 35 T3N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: S.S. MINNOW
Location ID: 449186



Photo 1. Photo taken from the northern location, facing West. Ditch and berm BMP installed around perimeter of location.



Photo 2. Photo taken from the northwest location, facing West. Sediment trap is IN-PROCESS of being constructed.

Inspection Photos
Location Name: S.S. MINNOW
Location ID: 449186



Photo 3. Photo taken from the northwest location, facing South. Sediment trap is IN-PROCESS of being constructed.



Photo 4. Photo taken from the northwest location, facing South. Ditch and berm BMP installed around perimeter of location.

Inspection Photos
Location Name: S.S. MINNOW
Location ID: 449186



Photo 5. Photo taken from the northwestern location, facing South. Sediment trap is IN-PROCESS of being constructed.



Photo 6. Photo taken from the western location, facing South. Ditch and berm BMP installed around perimeter of location.

Inspection Photos
Location Name: S.S. MINNOW
Location ID: 449186



Photo 7. Photo taken from the western location, facing Southeast, towards the topsoil stockpile.



Photo 8. Photo taken from the southwest location, facing East. Ditch and berm BMP installed around perimeter of location.

Inspection Photos
Location Name: S.S. MINNOW
Location ID: 449186



Photo 9. Photo taken from the southeast location, facing North. Ditch and berm BMP installed along perimeter of location.