

**Inspection Photos**  
**Location Name: George Gerhardt 2**  
**API: 05-123-08124**



**Photo from prior inspection for comparison**



**Photo 1: Stained soil at wellhead from prior inspection**

**Inspection Photos**  
**Location Name: George Gerhardt 2**  
**API: 05-123-08124**



**Photo 2: Stained soil at wellhead**