

Inspection Photos
Location Name: George Gerhardt 2
API: 05-123-08124



Photo from prior inspection for comparison



Photo 1: Stained soil at wellhead, looking SW