

Inspection Photos
Location Name: Marie Gerhardt B 4
API: 05-123-08603



Photo from prior inspection for comparison



Photo 1: Bradenhead at surface, stained soil at wellhead removed.