

**Inspection Photos**  
**Location Name: Marie Gerhardt B 5**  
**API: 05-123-08916**



**Photo from prior inspection for comparison**



**Photo 1: Weeds controlled, pipe removed. Unused pump jack on location.**

**Inspection Photos**  
**Location Name: Marie Gerhardt B 5**  
**API: 05-123-08916**



**Photo 2: Stained soil at wellhead**