

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2017

Submitted Date:

02/27/2017

Document Number:

679902306

**FIELD INSPECTION FORM**

Loc ID 305013 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 86610  
Name of Operator: CAERUS WASHCO LLC  
Address: 1001 17TH STREET - STE #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

| Contact Name   | Phone                | Email                           | Comment |
|----------------|----------------------|---------------------------------|---------|
| Grant, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com |         |
| Sprague, Chuck | 970-630-0214         | csprague@caerusoilandgas.com    |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 277590      | WELL | PR     | 04/06/2005  | GW         | 125-09259 | PECAR 31-24   | PR          |

**General Comment:**

[Form 10 in process](#)

| Location   |   |        |                 |
|--|---|--------|-----------------|
| <b>Lease Road:</b>                                     |   |        |                 |
| Type   | Access                                    |        |                 |
| comment:   | Two track through pasture                 |        |                 |
| Corrective Action:                                     |   | Date:  |                 |
| Overall Good: <input checked="" type="checkbox"/>      |   |        |                 |
| <b>Signs/Marker:</b>                                   |   |        |                 |
| Type   | OTHER                                     |        |                 |
| Comment:   | Lease sign by water tank                  |        |                 |
| Corrective Action:                                     |   | Date:  |                 |
| Type   | TANK LABELS/PLACARDS                      |        |                 |
| Comment:   | Metal sign by water tank                  |        |                 |
| Corrective Action:                                     |   | Date:  |                 |
| Type   | WELLHEAD                                  |        |                 |
| Comment:   | Lease sign by fiberglass shed             |        |                 |
| Corrective Action:                                     |   | Date:  |                 |
| <b>Emergency Contact Number:</b>                       |   |        |                 |
| Comment:   |   |        |                 |
| Corrective Action:                                     |   |        | Date: _____     |
| Overall Good: <input checked="" type="checkbox"/>      |   |        |                 |
| <b>Spills:</b>   |   |        |                 |
| Type   | Area                                      | Volume |                 |
| In Containment: No                                     |   |        |                 |
| Comment:   |   |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |                 |
| <b>Fencing/:</b>                                       |   |        |                 |
| Type   | TANK BATTERY                              |        |                 |
| Comment:   | Metal panels around water tank            |        |                 |
| Corrective Action:                                     |   | Date:  |                 |
| <b>Equipment:</b>                                      |   |        |                 |
| Type: Deadman # & Marked                               | # 4                                       |        | corrective date |
| Comment:   |   |        |                 |
| Corrective Action:                                     |   | Date:  |                 |
| Type: Plunger Lift                                     | # 1                                       |        |                 |
| Comment:   | Plunger lift in fiberglass shed           |        |                 |
| Corrective Action:                                     |   | Date:  |                 |
| Type: Vertical Separator                               | # 1                                       |        |                 |
| Comment:   | Vertical gas separator in fiberglass shed |        |                 |
| Corrective Action:                                     |   | Date:  |                 |

**Tanks and Berms:**

| Contents       | # | Capacity | Type           | Tank ID | SE GPS                |
|----------------|---|----------|----------------|---------|-----------------------|
| PRODUCED WATER | 1 | OTHER    | PBV FIBERGLASS |         | 39.874290,-102.247990 |

Comment: [Fiberglass water tank 50% buried](#)

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Paint**

|                  |         |
|------------------|---------|
| Condition        |         |
| Other (Content)  |         |
| Other (Capacity) | 210bbbs |
| Other (Type)     |         |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

Comment:

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 277590 Type: WELL API Number: 125-09259 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Central meter run for \(SIMMONS 1-24, 2-24, 42-24 & PECAR 33-24, 31-24, 32-24\) 1000' SE @ SIMMONS 1-24, 39.87239/-102.24543](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Other                   | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT