

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2017

Submitted Date:

03/01/2017

Document Number:

685502089

**FIELD INSPECTION FORM**

Loc ID 305423 Inspector Name: MONTOYA, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1625 BROADWAY STE 2200  
City: DENVER State: CO Zip: 80202

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277447	WELL	PR	08/02/2005	GW	123-22949	DECHANT D 7-23	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	OK		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	ROD IRON FENCE SE CORNER N40.14134 W-104.35343		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 277447 Type: WELL API Number: 123-22949 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: BRADENHEAD PLUMBED TO SURFACE

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass  
1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass  
Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input type="text"/>						
Corrective Action: <input type="text"/>						Date: _____
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

<u>COGCC Comments</u>		
Comment	User	Date
INTERMITTER CONTROLLER ON WELLHEAD	montoyaj	03/01/2017