

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2017

Submitted Date:

03/01/2017

Document Number:

666802951**FIELD INSPECTION FORM**

Loc ID 334629 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|--------------------|--|
| Axelson, Aaron | 970-230-0926 | aaxelson@vnrlc.com | Sr. Production Foreman |
| Ghan, Scott | | sghan@vnrlc.com | Sr. EH&S |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 283775 | WELL | PR | 05/17/2006 | GW | 045-11993 | CIRCLE B LAND 23B-35-692 | PR |
| 283989 | WELL | PR | 09/09/2006 | GW | 045-12059 | CIRCLE B LAND 13C-35-692 | PR |
| 283990 | WELL | PR | 06/23/2006 | GW | 045-12064 | CIRCLE B LAND 13A-35-692 | PR |
| 283992 | WELL | PR | 06/23/2006 | GW | 045-12063 | CIRCLE B LAND 23D-35-692 | PR |
| 284741 | WELL | PR | 06/23/2006 | GW | 045-12259 | CIRCLE B LAND 22A-35-692 | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Plunger Lift | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 0 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 0 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|-------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | PLASTIC AST | | , |
| Comment: | At wellhead, Bradenhead hooked up to tank, API number 05-045-12059 | | | | |
| Corrective Action: | | | | | Date: |

Paint

Condition Adequate

Other (Content)

Other (Capacity) 500gal

| | | | | | | |
|--------------------------|----------|---------------------|---------------------|-------------|-----------------------|--|
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Other | Adequate | Walls Sufficent | Base Sufficent | Adequate | | |
| Comment: Plastic tub | | | | | | |
| Corrective Action: | | | | Date: | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 6 | OTHER | STEEL AST | | 39.483061,-107.640608 | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| <u>Paint</u> | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) 250bbbs | | | | | | |
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| <u>Venting:</u> | | | | | | |
| Yes/No | YES | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| <u>Flaring:</u> | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 283775 | Type: | WELL | API Number: | 045-11993 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 283989 | Type: | WELL | API Number: | 045-12059 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 283990 | Type: | WELL | API Number: | 045-12064 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 283992 | Type: | WELL | API Number: | 045-12063 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 284741 | Type: | WELL | API Number: | 045-12259 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Rip Rap | Pass | | | | | |
| Berms | Pass | | | | | |
| | | Check Dams | Pass | | | |
| | | Culverts | Pass | | | |
| | | Rip Rap | Pass | | | |
| Ditches | Pass | | | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT