

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/15/2017

Submitted Date:

03/01/2017

Document Number:

666802953**FIELD INSPECTION FORM**

Loc ID 311695 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291309	WELL	PR	01/09/2008	GW	045-14329	GENTRY C3	PR
291310	WELL	PR	07/09/2007	GW	045-14328	GENTRY C2	PR
291311	WELL	PR	01/30/2008	GW	045-14327	GENTRY C1	PR
291312	WELL	PR	12/28/2007	GW	045-14326	GENTRY C4	PR
294140	WELL	XX	01/26/2015	LO	045-15270	GENTRY C11	XX
294141	WELL	PR	05/28/2009	GW	045-15271	GENTRY C9	PR
294143	WELL	PR	12/28/2007	GW	045-15272	GENTRY C8	PR
294177	WELL	PR	09/08/2015	GW	045-15297	GENTRY C10	PR
294178	WELL	PR	01/04/2008	GW	045-15298	GENTRY C5	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

1

Comment: Corrective Action: Date:

Type: Horizontal Heated Separator

9

Comment: Corrective Action: Date:

Type: Plunger Lift

3

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		39.521040,-107.682501
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

PaintCondition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Metal	Adequate		Walls Sufficent		Base Sufficient		Adequate		
Comment:									
Corrective Action:								Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS		
PRODUCED WATER		3	300 BBLS	STEEL AST			,		
Comment:		Centralized battery							

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Maintenance
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	291309	Type:	WELL	API Number:	045-14329	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291310	Type:	WELL	API Number:	045-14328	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	291311	Type:	WELL	API Number:	045-14327	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	291312	Type:	WELL	API Number:	045-14326	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	294140	Type:	WELL	API Number:	045-15270	Status:	XX	Insp. Status:	XX
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	294141	Type:	WELL	API Number:	045-15271	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	294143	Type:	WELL	API Number:	045-15272	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	294177	Type:	WELL	API Number:	045-15297	Status:	PR	Insp. Status:	PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: [Last posted production numbers Sept 2016](#)

Corrective Action: _____

Date: _____

Facility ID: 294178 Type: WELL API Number: 045-15298 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action: _____

Date: _____

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Rip Rap	Pass					
		Ditches	Pass			
		Gravel	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	295546	1433859	
	295546	1433859	