

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2017

Submitted Date:

03/01/2017

Document Number:

674703685**FIELD INSPECTION FORM**

Loc ID 334743 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-263-2716 | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 210890 | WELL | PR | 08/08/1997 | GW | 045-06648 | BARRETT ET AL GV 21-35 | PR |
| 286404 | WELL | PR | 08/28/2006 | GW | 045-12666 | WILLIAMS GM 544-35 | PR |
| 286406 | WELL | PR | 08/28/2006 | GW | 045-12664 | WILLIAMS GM 34-35 | PR |
| 286407 | WELL | PR | 08/28/2006 | GW | 045-12663 | WILLIAMS GM 227-35 | PR |
| 286408 | WELL | PR | 01/05/2007 | GW | 045-12662 | WILLIAMS GM 643-35 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Heated Separator | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 5 | | |

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 200 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|-------|--|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | Date: | |

Flaring:

| | | |
|--------------------|-------|--|
| Type | | |
| Comment: | | |
| Corrective Action: | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 210890 | Type: | WELL | API Number: | 045-06648 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286404 | Type: | WELL | API Number: | 045-12666 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286406 | Type: | WELL | API Number: | 045-12664 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286407 | Type: | WELL | API Number: | 045-12663 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286408 | Type: | WELL | API Number: | 045-12662 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |
| | | Compaction | Pass | | | |
| Ditches | Pass | | | | | |
| Compaction | Pass | | | | | |
| Check Dams | Pass | | | | | |
| | | Ditches | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT