



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is largely comprised of grasses such as smooth brome (*Bromus inermis*) and intermediate wheatgrass (*Thinopyron intermedium*) and weeds such as cheatgrass (*Bromus tectorum*).



Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4: View of the southern portion of the project area from the southeastern corner facing westward. Unused equipment should be removed.



Photo 5: View of Canada thistles (*Cirsium arvense*) from the previous growing season. These need treatment in 2017.



Photo 6: View of bull thistle (*Cirsium vulgare*) within the southern portion of the project area.