



**Photo 1: View of the western portion of the project area from the southwestern corner facing northward. Erosional channels are forming along this border. Revegetation is progressing and largely comprised of grasses such as Indian ricegrass (*Achnatherum hymenoides*), dropseed (*Sporobolus* sp.), and weeds such as cheatgrass (*Bromus tectorum*).**





**Photo 2: View of erosional channels forming in the southwestern portion of the project area from the southwestern corner facing northeastward.**





**Photo 3: View of erosional channels forming in the southeastern portion of the project area.**





**Photo 4: View of area in the southern portion of the working area where concentrated stormwater flows off of the well pad.**