



September 21, 2016 view north at Spill ID #447951 located on the south side of the Mt. Hope Unit Tank Battery inside temporary berms constructed after the spill.



September 21, 2016 view west at Spill ID #447951 and temporary containment berms on the south side of the tank battery.



September 21, 2016 view north at Spill ID #447951 area after the impacted soil had been scraped up and included with the Spill ID #446079 soil stockpile.



September 22, 2016 view southeast during the removal of impacted soil stockpile from the Spill ID #446079 and Spill ID #447951 spills.



September 22, 2016 view north of impacted soil stockpile related to Spill ID #446079 and Spill ID #447951.



September 22, 2016 view north at the former impacted soil stockpile area and secondary containment reconstruction.



September 22, 2016 view of the rebuilt secondary containment berm.