

Inspection Photos  
Location Name: Carl R. Deepe C 2  
API: 05-123-08992



**Photo 1: Stained soil at wellhead, no bradenhead**