

Inspection Photos
Location Name: Martin T Hart F Unit 1
API: 05-123-08695



Photo from prior inspection for comparison purposes



Photo 1: Weeds controlled

Inspection Photos
Location Name: Martin T Hart F Unit 1
API: 05-123-08695



Photo from prior inspection for comparison purposes



Photo 2: Soil is being remediated

Inspection Photos
Location Name: Martin T Hart F Unit 1
API: 05-123-08695



Photo from prior inspection for comparison purposes



Photo 3: Stained soil present in vertical separator house

Inspection Photos
Location Name: Martin T Hart F Unit 1
API: 05-123-08695



Photo 4: Paint is fading from production tanks

