

Photo#1:

View from NE Corner to SW.



Photo#2:

View from SW Corner to NE



March 3, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: URSA BMC D Pad Loc#446582

Photo#3:

Water Truck applying Dust Control.

\*



Photo#4:

Area at SW corner Repaired/Reclaimed by Pipe line Company; outside LOD



March 3, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: URSA BMC D Pad Loc#446582

Photo#5:

Top Soil has been installed over Berm at South edge of Location..

Photo#6:



March 3, 2017