

Inspection Photos
Location Name: Elkhorn Company B 2
API: 05-123-08390



Photo from prior inspection for comparison purposes



Photo 1: Wellhead, looking SW. Sign has been placed, weeds around wellhead.