

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/15/2017

Submitted Date:

03/01/2017

Document Number:

666802953**FIELD INSPECTION FORM**

Loc ID 311695 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291309	WELL	PR	01/09/2008	GW	045-14329	GENTRY C3	PR
291310	WELL	PR	07/09/2007	GW	045-14328	GENTRY C2	PR
291311	WELL	PR	01/30/2008	GW	045-14327	GENTRY C1	PR
291312	WELL	PR	12/28/2007	GW	045-14326	GENTRY C4	PR
294140	WELL	XX	01/26/2015	LO	045-15270	GENTRY C11	XX
294141	WELL	PR	05/28/2009	GW	045-15271	GENTRY C9	PR
294143	WELL	PR	12/28/2007	GW	045-15272	GENTRY C8	PR
294177	WELL	PR	09/08/2015	GW	045-15297	GENTRY C10	PR
294178	WELL	PR	01/04/2008	GW	045-15298	GENTRY C5	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

3

Comment: Corrective Action: Date:

Type: Horizontal Heated Separator

9

Comment: Corrective Action: Date:

Type: Emission Control Device

1

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	300 BBLS	STEEL AST		,	
Comment:	Centralized battery					
Corrective Action:						Date: <input type="text"/>

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID		SE GPS		
CONDENSATE		3	300 BBLS	STEEL AST				39.521040,-107.682501		
Comment:										

Corrective Action:					Date:	
--------------------	--	--	--	--	-------	--

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	291309	Type:	WELL	API Number: 045-14329	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	291310	Type:	WELL	API Number: 045-14328	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	291311	Type:	WELL	API Number: 045-14327	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	291312	Type:	WELL	API Number: 045-14326	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	294140	Type:	WELL	API Number: 045-15270	Status: XX	Insp. Status: XX
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	294141	Type:	WELL	API Number: 045-15271	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	294143	Type:	WELL	API Number: 045-15272	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	294177	Type:	WELL	API Number: 045-15297	Status: PR	Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: [Last posted production numbers Sept 2016](#)

Corrective Action: _____

Date: _____

Facility ID: 294178 Type: WELL API Number: 045-15298 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action: _____

Date: _____

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Berms	Pass					
		Gravel	Pass			
		Ditches	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401223121	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4088384