

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2017

Submitted Date:

02/28/2017

Document Number:

672500384**FIELD INSPECTION FORM**

Loc ID 305447	Inspector Name: Gomez, Jason	On-Site Inspection <input type="checkbox"/>	<b>Status Summary:</b>  <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED							
2A Doc Num: _____			<b>Findings:</b> 3 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested							
<b>Operator Information:</b> OGCC Operator Number: <u>10633</u> Name of Operator: <u>CRESTONE PEAK RESOURCES OPERATING LLC</u> Address: <u>370 17TH STREET #2170</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>										
<b>Contact Information:</b>										
<table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td></td> <td></td> <td>Cogcc.inspections@crestonepr.com</td> <td></td> </tr> </table>				Contact Name	Phone	Email	Comment			Cogcc.inspections@crestonepr.com
Contact Name	Phone	Email	Comment							
		Cogcc.inspections@crestonepr.com								

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277773	WELL	PR	09/30/2009	GW	123-22988	WOOLLEY 12-7	PR
434333	WELL	DG	10/17/2016	LO	123-38104	Woolley Sosa 2A-7H-E168	DG
434334	WELL	DG	11/03/2016	LO	123-38105	Woolley Becky 2F-7H-E168	DG
434335	WELL	DG	10/23/2016	LO	123-38106	Woolley Sosa 2D-7H-E168	DG
434336	WELL	DG	11/01/2016	LO	123-38107	Woolley Becky 2D-7H-E168	DG
434337	WELL	DG	10/18/2016	LO	123-38108	Woolley Sosa 2B-7H-E168	DG
434338	WELL	DG	10/30/2016	LO	123-38109	Woolley Becky 2B-7H-E168	DG
434339	WELL	DG	10/24/2016	LO	123-38110	Woolley Sosa 2E-7H-E168	DG
434340	WELL	DG	10/29/2016	LO	123-38111	Woolley Becky 2A-7H-E168	DG
434341	WELL	DG	11/02/2016	LO	123-38112	Woolley Becky 2E-7H-E168	DG
434342	WELL	DG	10/26/2016	LO	123-38113	Woolley Sosa 2F-7H-E168	DG
434343	WELL	DG	11/05/2016	LO	123-38114	Woolley Becky 2H-7H-E168	DG
436731	WELL	DG	10/31/2016	LO	123-39241	Woolley Becky 2C-7H-E168	DG
436733	WELL	DG	11/04/2016	LO	123-39242	Woolley Becky 2G-7H-E168	DG
436738	WELL	DG	10/19/2016	LO	123-39245	Woolley Sosa 2C-7H-E168	DG
436739	WELL	DG	10/30/2016	LO	123-39246	Woolley Sosa 2G-7H-E168	DG

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	#		corrective date
Comment:	approx 32' sound walls around location		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	Field Flare	
Comment:	not in use at the time of inspection	
Corrective Action:		Date:



Multi-Well: <u>YES</u>	Disposal Location: <u>Waste Management</u>
Comment: <input type="text"/>	
Corrective Action: <input type="text"/>	Date: <input type="text"/>

Facility ID: <u>434334</u>	Type: <u>WELL</u>	API Number: <u>123-38105</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434335</u>	Type: <u>WELL</u>	API Number: <u>123-38106</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434336</u>	Type: <u>WELL</u>	API Number: <u>123-38107</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434337</u>	Type: <u>WELL</u>	API Number: <u>123-38108</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434338</u>	Type: <u>WELL</u>	API Number: <u>123-38109</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434339</u>	Type: <u>WELL</u>	API Number: <u>123-38110</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434340</u>	Type: <u>WELL</u>	API Number: <u>123-38111</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434341</u>	Type: <u>WELL</u>	API Number: <u>123-38112</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434342</u>	Type: <u>WELL</u>	API Number: <u>123-38113</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434343</u>	Type: <u>WELL</u>	API Number: <u>123-38114</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>436731</u>	Type: <u>WELL</u>	API Number: <u>123-39241</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>436733</u>	Type: <u>WELL</u>	API Number: <u>123-39242</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>436738</u>	Type: <u>WELL</u>	API Number: <u>123-39245</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>436739</u>	Type: <u>WELL</u>	API Number: <u>123-39246</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment: [Not in use at time of inspection](#)

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass			Vehicle Tracking	Pass	
Compaction	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass					
Rip Rap	Pass					
Berms	Pass	Compaction	Pass	Covering Materials	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401223097	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4088364">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4088364</a>