

Inspection Photos
Location Name: Speaker P
API: 05-123-05490



Photo from prior inspection for comparison



Photo 1: Deadman marked

Inspection Photos
Location Name: Speaker P
API: 05-123-05490



Photo from prior inspection for comparison



Photo 2: No capacity on production tank

Inspection Photos
Location Name: Speaker P
API: 05-123-05490



Photo from prior inspection for comparison



Photo 3: Stained soil removed

Inspection Photos
Location Name: Speaker P
API: 05-123-05490



Photo from prior inspection for comparison



Photo 4: Stained soil removed

Inspection Photos
Location Name: Speaker P
API: 05-123-05490



Photo from prior inspection for comparison



Photo 5: Stained soil removed

Inspection Photos
Location Name: Speaker P
API: 05-123-05490



Photo from prior inspection for comparison




Photo 6: Stained soil removed. Some staining at treater.

Inspection Photos
Location Name: Speaker P
API: 05-123-05490



Photo 7: Weeds on pit.