

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2017

Submitted Date:

03/09/2017

Document Number:

666803008**FIELD INSPECTION FORM**

Loc ID 423439	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 17 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>VANGUARD OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412841	WELL	PR	07/21/2011	GW	045-18667	MILLER 33D-6-791	PR
412843	WELL	PR	07/21/2011	GW	045-18666	MILLER 33C-6-791	PR
412844	WELL	PR	06/06/2011	GW	045-18665	MILLER 33B-6-791	PR
412845	WELL	PR	06/06/2011	GW	045-18664	MILLER 33A-6-791	PR
412846	WELL	PR	07/21/2011	GW	045-18663	MILLER FEDERAL 23D-6-791	PR
412847	WELL	PR	06/06/2011	GW	045-18662	MILLER FEDERAL 23C-6-791	PR
412848	WELL	PR	06/06/2011	GW	045-18661	MILLER FEDERAL 23B-6-791	PR
412849	WELL	PR	07/20/2011	GW	045-18660	MILLER FEDERAL 24D-31-691	PR
412850	WELL	PR	07/20/2011	GW	045-18659	MILLER FEDERAL 24C-31-691	PR
412853	WELL	PR	07/21/2011	GW	045-18657	MILLER FEDERAL 24A-31-691	PR
412910	WELL	PR	07/21/2011	GW	045-18658	MILLER FEDERAL 24B 31-691	PR

General Comment:

Tank battery on location ID 383325

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

1

Comment: Trailer mounted, temporary

Corrective Action:

Date:

Type: Plunger Lift

11

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

3

Comment: Chemical units

Corrective Action:

Date:

Type: Horizontal Heated Separator

11

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment: Trailer mounted, temporary

Corrective Action:

Date:

Venting:

Yes/No YES

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	412841	Type:	WELL	API Number:	045-18667	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	412843	Type:	WELL	API Number:	045-18666	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	412844	Type:	WELL	API Number:	045-18665	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	412845	Type:	WELL	API Number:	045-18664	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	412846	Type:	WELL	API Number:	045-18663	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	412847	Type:	WELL	API Number:	045-18662	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	412848	Type:	WELL	API Number:	045-18661	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	412849	Type:	WELL	API Number:	045-18660	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	412850	Type:	WELL	API Number:	045-18659	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	412853	Type:	WELL	API Number:	045-18657	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	412910	Type:	WELL	API Number:	045-18658	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: [On location ID 383325](#)

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Rip Rap	Pass			
		Culverts	Pass			
Ditches	Pass					
Sediment Traps	In Process					
		Sediment Traps	Pass			
		Check Dams	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT