

Inspection Photos
Location Name: Hazel McHale 1
API: 05-123-07643



Photo from prior inspection for comparison



Photo 1: Weeds controlled

Inspection Photos
Location Name: Hazel McHale 1
API: 05-123-07643



Photo 2: Stained soil at produced water loadout



Photo 3: Stained soil at manifold

Inspection Photos
Location Name: Hazel McHale 1
API: 05-123-07643



03.09.2017 13:38

Photo 4: No sign or label for vault



03.09.2017 13:54

Photo 5: No labels on production tank

Inspection Photos
Location Name: Hazel McHale 1
API: 05-123-07643



Photo 6: Stained soil and leak at separator