



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	SATISFACTORY		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	PANEL		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 6		corrective date
Comment:	Refer to inspection # 681901553 for information concerning shared battery and equipment.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	Refer to inspection # 681901553 for information concerning shared battery and equipment.				
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 416431 Type: WELL API Number: 123-31372 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 416432 Type: WELL API Number: 123-31373 Status: PR Insp. Status: PR

**Cement**

Cement Contractor  
Contractor Name: SCHLUMBERGER Contractor Phone: \_\_\_\_\_

Surface Casing  
Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing  
Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing  
Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations  
Depth Plugs(feet range): \_\_\_\_\_ Cement Volume (sx): \_\_\_\_\_  
Good Return During Job: \_\_\_\_\_ Cement Type: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 416433 Type: WELL API Number: 123-31374 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 416437 Type: WELL API Number: 123-31377 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In     Temporarily Abandoned    Reminder: \_\_\_\_\_

Comment:

Corrective Action:     Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:     Date: \_\_\_\_\_

Facility ID: 416455    Type: WELL    API Number: 123-31384    Status: PR    Insp. Status: PR

**Idle Well**

Purpose:  Shut In     Temporarily Abandoned    Reminder: \_\_\_\_\_

Comment:

Corrective Action:     Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:     Date: \_\_\_\_\_

Facility ID: 416465    Type: WELL    API Number: 123-31389    Status: PR    Insp. Status: PR

**Idle Well**

Purpose:  Shut In     Temporarily Abandoned    Reminder: \_\_\_\_\_

Comment:

Corrective Action:     Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:     Date: \_\_\_\_\_