

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2017

Submitted Date:

03/08/2017

Document Number:

674703720**FIELD INSPECTION FORM**
 Loc ID 334727 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258180	WELL	PR	10/05/2000	GW	045-07624	BORUCH GM 44-11	PR
269666	WELL	PR	02/13/2004	GW	045-09392	BORUCH GM 344-11	PR
279068	WELL	PR	03/23/2006	GW	045-10981	BORUCH GM 534-11	PR
279069	WELL	PR	03/21/2006	GW	045-10982	BORUCH GM 34-11	PR
279070	WELL	PR	04/04/2006	GW	045-10983	BORUCH GM 334-11	PR
279071	WELL	PR	04/03/2006	GW	045-10984	BORUCH GM 444-11	PR
279072	WELL	PR	03/23/2006	GW	045-10985	BORUCH GM 544-11	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	258180	Type:	WELL	API Number:	045-07624	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	269666	Type:	WELL	API Number:	045-09392	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	279068	Type:	WELL	API Number:	045-10981	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	279069	Type:	WELL	API Number:	045-10982	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	279070	Type:	WELL	API Number:	045-10983	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	279071	Type:	WELL	API Number:	045-10984	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	279072	Type:	WELL	API Number:	045-10985	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Gravel	Pass			
Berms	Pass					
Seeding	In Process					
		Culverts	Pass			
		Ditches	Pass			
Compaction	Pass					
Ditches	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT