

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/03/2017

Submitted Date:

03/03/2017

Document Number:

675203926**FIELD INSPECTION FORM**

Loc ID 435460	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				<b>Findings:</b> <u>3</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Sarah		sarah.freeman@state.co.us	<a href="#">NW Permitting</a>
TEP, Energy		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435462	WELL	XX	12/16/2013	LO	045-22274	Bosely SG 542-21	ND
435464	WELL	XX	12/16/2013	LO	045-22276	Bosely SG 533-22	ND
435469	WELL	XX	12/16/2013	LO	045-22281	Bosely SG 443-21	ND
435470	WELL	XX	12/16/2013	LO	045-22282	Bosely SG 642-21	ND
435471	WELL	XX	12/16/2013	LO	045-22283	Bosely SG 243-21	ND
435473	WELL	XX	12/16/2013	LO	045-22285	Bosely SG 32-22	ND
435475	WELL	XX	12/16/2013	LO	045-22287	Bosely SG 343-21	ND

**General Comment:**

[Permits have expired for API's 045-22274, 045-22276, 045-22281, 045-22282, 045-22283, 045-22285, and 045-22287.](#)

**Inspected Facilities**

Facility ID: <u>435462</u>	Type: <u>WELL</u>	API Number: <u>045-22274</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>435464</u>	Type: <u>WELL</u>	API Number: <u>045-22276</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>435469</u>	Type: <u>WELL</u>	API Number: <u>045-22281</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>435470</u>	Type: <u>WELL</u>	API Number: <u>045-22282</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>435471</u>	Type: <u>WELL</u>	API Number: <u>045-22283</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>435473</u>	Type: <u>WELL</u>	API Number: <u>045-22285</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>435475</u>	Type: <u>WELL</u>	API Number: <u>045-22287</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401224786	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4089995">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4089995</a>