

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401227650

Date Received:

03/10/2017

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

449423

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	Phone Numbers
Address: <u>1775 SHERMAN STREET - STE 3000</u>		Phone: <u>(970) 506-9272</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>		Mobile: <u>(970) 373-6581</u>
Contact Person: <u>Zack Liesenfeld</u>		Email: <u>Zack.Liesenfeld@pdce.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401221976

Initial Report Date: 03/01/2017 Date of Discovery: 02/28/2017 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWNE SEC 10 TWP 5N RNG 64W MERIDIAN 6

Latitude: 40.419330 Longitude: -104.536150

Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: FLOWLINE Facility/Location ID No 330540
 No Existing Facility or Location ID No.
 Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: CROP LAND Other(Specify): _____

Weather Condition: Cloudy and cool

Surface Owner: FEE Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area
 As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

PDC Energy discovered a reportable produced water release on the Wacker 31, 32-10 during flowline integrity testing. Upon discovery the facility was immediately shut in and vault bottomed out.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
3/1/2017	COGCC	Rick Allison	-	Via Email
3/1/2017	Weld County	Roy Rudisill	-	Via Email
3/1/2017	Land Owner	NA	-	Via Phone Call

SPILL/RELEASE DETAIL REPORTS

#1 Supplemental Report Date: 03/08/2017

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	13	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) Soil Groundwater Surface Water Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): _____ Width of Impact (feet): _____

Depth of Impact (feet BGS): _____ Depth of Impact (inches BGS): _____

How was extent determined?

On February 28, 2017, a produced water release was discovered at the Wacker 31, 32-10 facility during production line integrity testing. It is estimated that approximately 13 barrels of produced water were released outside of secondary containment. The tank and production lines will remain shut-in until repairs may be completed. A sub-surface site investigation will be conducted and summarized in a forthcoming report. A topographic map is included as Figure 1.

Soil/Geology Description:

Otero sandy loam, 1 to 3 percent slopes.

Depth to Groundwater (feet BGS) 38 Number Water Wells within 1/2 mile radius: 7

If less than 1 mile, distance in feet to nearest

Water Well	<u>1525</u>	None <input type="checkbox"/>	Surface Water	<u>2575</u>	None <input type="checkbox"/>
Wetlands	_____	None <input checked="" type="checkbox"/>	Springs	_____	None <input checked="" type="checkbox"/>
Livestock	_____	None <input checked="" type="checkbox"/>	Occupied Building	<u>1968</u>	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

CORRECTIVE ACTIONS

#1	Supplemental Report Date:	03/08/2017		
Cause of Spill (Check all that apply)		<input type="checkbox"/> Human Error	<input checked="" type="checkbox"/> Equipment Failure	<input type="checkbox"/> Historical-Unknown
		<input type="checkbox"/> Other (specify) _____		
Describe Incident & Root Cause (include specific equipment and point of failure)				
Failure identified during annual flowline integrity testing due to a damaged connection at the water vault.				
Describe measures taken to prevent the problem(s) from reoccurring:				
Damaged connection will be replaced and routine integrity inspections will continue.				
Volume of Soil Excavated (cubic yards): 0				
Disposition of Excavated Soil (attach documentation)		<input type="checkbox"/> Offsite Disposal	<input type="checkbox"/> Onsite Treatment	
		<input type="checkbox"/> Other (specify) _____		
Volume of Impacted Ground Water Removed (bbls):		0		
Volume of Impacted Surface Water Removed (bbls):		0		

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: Corrective Actions Completed (documentation attached)
 Work proceeding under an approved Form 27
Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Zack Liesenfeld
Title: EHS Professional Date: 03/10/2017 Email: Zack.Liesenfeld@pdce.com

<u>COA Type</u>	<u>Description</u>

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401230217	TOPOGRAPHIC MAP

Total Attach: 1 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)