

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/10/2017

Submitted Date:

03/10/2017

Document Number:

675203992

**FIELD INSPECTION FORM**

Loc ID 334093 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 100185  
Name of Operator: ENCANA OIL & GAS (USA) INC  
Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-

**Contact Information:**

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	<a href="#">All Inspections</a>
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	<a href="#">Petroleum Engineer</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275435	WELL	PR	09/21/2010	GW	045-13543	SATTERFIELD 10-7 (C10OU)	PR
275436	WELL	PR	11/18/2010	GW	045-13542	SATTERFIELD 10-2 (C10OU)	PR
275437	WELL	PR	03/20/2012	GW	045-13541	SATTERFIELD 10-3 (C10OU)	PR
275438	WELL	PR	08/16/2005	GW	045-13544	SATTERFIELD 10-6 (C10OU)	PR
281721	WELL	PR	09/04/2014	GW	045-11500	SATTERFIELD FEDERAL 10-4 (C10OU)	PR
281722	WELL	PR	08/01/2013	GW	045-11501	SATTERFIELD FEDERAL 10-5 (C10OU)	PR
298911	WELL	PR	03/12/2010	GW	045-17474	SATTERFIELD FEDERAL 10-3H (C10OU)	PR
420444	WELL	PR	10/21/2011	GW	045-20206	KEINATH FEDERAL 9-14H (C10OU)	PR
420447	WELL	PR	10/19/2011	GW	045-20207	FIVE R 15-1HM (C10OU)	PR
420500	WELL	PR	10/19/2011	GW	045-20211	KEINATH FEDERAL 9-12H (C10OU)	PR
421158	WELL	PR	10/16/2011	GW	045-20325	KEINATH FEDERAL 9-12H2 (C10OU)	PR

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	STEEL AST		,
Comment: <a href="#">Blowdown tank</a>					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Same as condensate
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	300 BBLS	STEEL AST		

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:	
Corrective Action:	Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: <u>275435</u>	Type: <u>WELL</u>	API Number: <u>045-13543</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>275436</u>	Type: <u>WELL</u>	API Number: <u>045-13542</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>275437</u>	Type: <u>WELL</u>	API Number: <u>045-13541</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>275438</u>	Type: <u>WELL</u>	API Number: <u>045-13544</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>281721</u>	Type: <u>WELL</u>	API Number: <u>045-11500</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>281722</u>	Type: <u>WELL</u>	API Number: <u>045-11501</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298911</u>	Type: <u>WELL</u>	API Number: <u>045-17474</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>420444</u>	Type: <u>WELL</u>	API Number: <u>045-20206</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>420447</u>	Type: <u>WELL</u>	API Number: <u>045-20207</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>420500</u>	Type: <u>WELL</u>	API Number: <u>045-20211</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>421158</u>	Type: <u>WELL</u>	API Number: <u>045-20325</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Retention Ponds	Pass					
Berms	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT