

Inspection Photos
Location Name: Dwight G Hanks B 1
API: 05-123-07487



Photo from prior inspection for comparison



Photo 1: Weeds at berm controlled

Inspection Photos
Location Name: Dwight G Hanks B 1
API: 05-123-07487



Photo from prior inspection for comparison



Photo 2: Stained soil in separator house

Inspection Photos
Location Name: Dwight G Hanks B 1
API: 05-123-07487



Photo 3: Stained soil at wellhead



Photo 4: Stained soil at pipes, tank

Inspection Photos
Location Name: Dwight G Hanks B 1
API: 05-123-07487



Photo 5: Stained soil at loadout