

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/10/2017

Submitted Date:

03/10/2017

Document Number:

666803013**FIELD INSPECTION FORM**

Loc ID 324423 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292166	WELL	PR	12/29/2007	GW	045-14610	FEDERAL 11-15A(RJ11)	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 1

Comment: Corrective Action: Date: 

Type: Plunger Lift

# 1

Comment: Corrective Action: Date: 

Type: Gas Meter Run

# 1

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		39.452510,-107.852718
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

**Paint**Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER			,
Comment:					

Corrective Action:		Date:	
<b>Paint</b>			
Condition	Adequate		
Other (Content)			
Other (Capacity) 500gal			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Comment:			
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: 292166	Type: WELL	API Number: 045-14610	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:				Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Rip Rap	Pass			
Retention Ponds	Pass					
Berms	Pass					
		Ditches	Pass			
		Culverts	Pass			
Gravel	Pass					
		Sediment Traps	Pass			
Seeding	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT