

# Interim Reclamation and Stormwater Inspection

February 27, 2017

Operator: CONOCO PHILLIPS COMPANY - # 19160

API: 005-07179

Arapahoe County, CO

SWSW Section 34 T4S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Grimm 34 #4H  
API: 05-005-07179



Google Earth aerial imagery taken June 14, 2016, and overlaid with field collected data on February 27, 2017 using a Trimble handheld GPS. Construction disturbance in red (6.87 acres) and current production area in blue (3.40 acres). The approved 2A was permitted for 5.10 acres of disturbance during construction.

Inspection Photos  
Location Name: Grimm 34 #4H  
API: 05-005-07179



**Photo 1.** Photo of well sign at entrance of location.



**Photo 2.** Photo taken from entrance of location, facing Southwest. Culvert installed with rip rap as outlet protection.



Inspection Photos  
Location Name: Grimm 34 #4H  
API: 05-005-07179



**Photo 3.** Photo taken from entrance of location along the current interim area, facing Northwest, towards the production area. Rip rap and wattles installed along the interim area and ditch BMP area.



**Photo 4.** Photo taken from entrance of location along the current interim area, facing North. Culvert installed with rip rap as inlet protection.

Inspection Photos  
Location Name: Grimm 34 #4H  
API: 05-005-07179



**Photo 5.** Photo taken from the southeast location along the current interim area, facing North. Wattles installed throughout the interim, west-facing slope area.



**Photo 6.** Photo taken from the northeast location along the current interim area, facing West. Wattles installed throughout the interim, south-facing slope area.



Inspection Photos  
Location Name: Grimm 34 #4H  
API: 05-005-07179



**Photo 7.** Overview photo taken from the northern location, facing South.



**Photo 8.** Overview photo taken from the northern location, facing Southwest.

Inspection Photos  
Location Name: Grimm 34 #4H  
API: 05-005-07179



**Photo 9.** Photo taken from the northern location along the current interim area, facing West. Wattles installed throughout the ditch BMP area.



**Photo 10.** Photo taken from the northwest location along the current interim area, facing South. Wattles installed throughout the ditch BMP area.



Inspection Photos  
Location Name: Grimm 34 #4H  
API: 05-005-07179



**Photo 11.** Photo taken from the western location along the current interim area, facing East. Sediment trap installed with armored outlet protection. Did not observe any sediment discharge at the sediment trap location.



**Photo 12.** Photo taken from the southwest location along the current interim area, facing Southeast. Sediment trap installed with armored outlet protection. Did not observe any sediment discharge at the sediment trap location.